

RATIO SPREAD	12.11
RATIO STEPS	
REV/1	-0.66
1/2	1.54
2/3	1.53
3/4	1.40
4/5	1.21
5/6	1.26
6/7	1.30
7/8	1.15
8/9	1.63